

Tree schedule				
Tree No	Species	Category	RPA Radius	Tree Works
All retained trees & hedges				
T1	Lime	A	7.2	-
T2	Lime	C	1.8	-
T3	Ash	C	1.8	-
T4	Lime	A	6.6	-
T5	False acacia	C	8.4	-
T6	Norway maple	A	8.1	-
T7	Norway maple	B	5.4	-
T8	Norway maple, ash	B	10.2	-
T9	Sycamore	B	6.3	-
T10	Horse chestnut	B	9.6	-
T11	Norway maple	C	4.5	-
T12	Sycamore	B	6.6	-
T13	Lime	C	1.8	-
T14	Horse chestnut	B	10.5	-
T15	Ash	C	1.8	-
T16	Horse chestnut	B	9.9	-
T17	False acacia	C	5.4	-
T18	Lime	C	1.8	-
T19	Ash	A	9.6	-
T20	Elm	C	7.2	-
T21	Oak	B	4.5	-
T22	Oak	A	6.6	-
T23	Horse chestnut	C	5.4	-
T24	London plane	A	9.0	-
T25	Ash	C	9.6	-
T26	London plane	B	3.6	-
T27	London plane	B	4.2	-
T28	London plane	B	4.5	-
T29	Red oak	B	3.6	-
T30	London plane	C	2.4	-
T31	Poplar	B	15.0	-
T32	Oak	C	2.4	-
T33	Poplar	C	10.8	Fell
T34	Beech	B	6.6	-
T35	Poplar	B	13.2	-
T36	Poplar	C	9.0	-
T37	Poplar	C	9.0	-
T38	Poplar	U	8.4	Fell for management
T39	Poplar	U	8.4	Fell for management
T40	London plane	B	3.8	-
T41	Ash	U	7.8	Fell for management
T42	London plane	A	10.8	-
T43	Horse chestnut	B	13.2	-
T44	London plane	A	15.0	-
T45	London plane	A	12.9	-
T46	London plane	A	11.7	-
H47	Privet	C	1.8	Fell part
G48	Yew, fir	C	2.4	-
T49	Blue spruce	C	2.4	Fell
T50	Horse chestnut	C	1.8	Fell
T51	Copper beech	U	7.8	Fell for management
T52	Beech	U	11.4	Fell for management
T53	Lime	B	9.3	-
T54	Copper beech	B	5.1	-
H55	Leyland cypress	C	3.6	Fell part
G56	Oak, ash, laurel	C	3.6	Fell
G57	Cherry, elder	C	3.6	Fell
G58	Birch, field maple	C	1.8	Fell
G59	Birch	C	1.8	-
T60	Turkey oak	A	9.0	-
T61	Turkey oak	A	8.4	-
T62	Beech	B	6.3	-
T63	Lime	B	10.5	-
T64	Beech	B	4.8	-
T65	Oak	A	9.9	-
T66	Lime	A	10.5	-
T67	Copper beech	B	6.9	-
T68	Beech	C	2.4	-
T69	Copper beech	A	7.8	-
T70	Copper beech	B	8.4	-
T71	Copper beech	A	8.4	-
T72	Copper beech	A	7.2	-
T73	Horse chestnut	U	12.9	Fell for management
T74	Oak	A	12.0	-
T75	Beech	U	8.4	Fell for management
T76	Oak	A	11.4	-
T77	Lime	B	7.2	-
T78	Lime	A	9.9	-
T79	Oak	A	7.8	-
T80	Sweet chestnut	C	1.8	-
T81	Sweet chestnut	C	1.2	-
T82	Oak	B	4.8	-
T83	Oak	B	6.0	-
T84	Oak	B	5.4	-
T85	Oak	A	7.2	-
T86	Oak	B	6.3	-
T87	Sycamore	B	8.4	-
T88	Lime	B	10.2	-
T89	Lime	A	10.5	-
T90	Lime	A	11.4	-
T91	Lime	A	11.7	-
T92	Lime	B	12.0	-
T93	Lime	A	11.1	-
T94	Lime	A	11.4	-
T95	Lime	A	11.1	-
T96	Lime	B	10.2	-
T97	Lime	A	13.2	-
T98	Sycamore	B	8.4	-
T99	Oak	C	1.8	-
T100	False acacia	C	8.4	-
T101	Norway maple	B	5.7	-
T102	Tree of heaven	B	9.9	-
T103	Maple	A	14.1	-
T104	Norway maple	B	6.0	-
T105	Tree of heaven	C	4.2	-
T106	Horse chestnut	C	6.0	-
T107	Ash	B	7.2	-
T108	Tree of heaven	C	3.6	-
T109	London plane	B	15.0	-
T110	Norway maple	B	8.4	-
T111	Ash	B	8.4	-
T112	Ash	C	5.4	-
T113	Ash	B	10.2	-
G114	Ash, Norway maple, oak	B	4.8	-
T115	Lime	A	9.6	-
T116	Turkey oak	B	9.0	-
T117	Lime	B	8.4	-
T118	Horse chestnut	B	7.8	-
T119	Norway maple	B	7.2	-
T120	Norway maple	B	7.8	-
T121	Horse chestnut	C	7.2	-
T122	Lime	B	7.2	-
T123	Horse chestnut	B	9.0	-
G124	Tree of heaven	C	2.4	Fell
G125	Tree of heaven	C	2.4	Fell
G126	Leyland cypress	C	4.8	Fell
G127	Holly, yew	C	5.4	-
T128	Cedar of Lebanon	A	15.0	-
T129	Golden false acacia	U	7.2	Fell for management
T130	Atlantic cedar	A	7.2	-
T131	Sweetgum	A	3.0	-
T132	False acacia	B	2.4	-
T133	Golden false acacia	U	5.4	Fell for management
G134	Yew	B	5.4	-
T135	Blue spruce	B	4.8	-

Areas of existing hard surfacing that may be upgraded during works. No excavation to be undertaken below the existing sub-base into the soil below. New surfacing will be permeable wherever possible.

Areas of existing hard surfacing that may be upgraded during works. No excavation to be undertaken below the existing sub-base into the soil below. New surfacing will be permeable wherever possible.

Existing footpath to be retained. Some areas of hard standing within nursery will be removed and returned to soft landscaping. No excavation to be undertaken into the soil below the sub-base.

Installation of ground protection over any exposed RPA outside the barriers for the duration of activity to be replaced with new no-dig, permeable surfacing.

Areas of existing hard surfacing that may be upgraded during works. No excavation to be undertaken below the existing sub-base into the soil below. New surfacing will be permeable wherever possible.

- BS category A Trees of high quality
- BS category B Trees of moderate quality
- BS category C Trees of low quality
- BS category U Trees unsuitable for retention
- Trees to be removed
- Proposed layout
- Estimated tree positions not included on original land survey and/or adjusted crown spreads
- Construction exclusion zone (CEZ) to be protected by fencing and/or ground protection
- Precautionary Areas
- Root protection area (RPA) boundaries for category A and B trees
- Root protection area (RPA) boundaries for category C trees

Scale: 1:500 @ A0

Tree protection plan
Location of trees, categorisation & protection/management proposals at Gunnersbury Park, Ealing

Permission is granted to scale from this drawing for Local Authority Planning Approval purposes relating to tree protection measures only. Where applicable this drawing is to be read in conjunction with the arboricultural report. This drawing is the copyright of Barrell Tree Consultancy 2015. ©

This drawing to be reproduced in colour only.

Barrell Plan Ref: 15323-BT2

Provided Plan Refs: Gunnersbury WD Survey Master Nov14/V2004.dwg & 3399-ASP-ST4-XX-M3-A-MODEL_15_vita-giannini@s-parchitects - Floor Plan ...dwg